

PSB-2005-052-A	Date: 19 December, 2005
Title	L2800HST & L3400HST; PTO Cams
Group Code	PT06
Product Line	L-Series
Model Number (s)	L2800HST, L3400HST

Service Information

SUBJECT:

On HST MODELS, a "Ratcheting Noise" may be heard during **engine de-acceleration** while the rear PTO is **engaged**.

This noise results from the overrunning action of the PTO clutch cams.

SOLUTION:

A RUNNING PRODUCTION CHANGE HAS BEEN ADOPTED.

The old style cams have been replaced with new "solid type" style, engagement cams.

PRODUCTION CHANGE WAS IMPLIMENTED AS PER THE FOLLOWING

L2800F	10929-UP
L2800DT/HST	57745-UP
L3400F	10547-UP
L3400DT/HST	61733-UP

Service Drawings



Old Style Clutch Cams (P/N TC220-99980)



New Style Clutch Cams (P/N TC220-99990)

Parts Information

Part Number	Part Name
TC220-99990	Kit, Cam Clutch / PTO

Warranty Information

Service Information Only