



hitting the  
frame rail

This image shows a close-up of a mechanical assembly, likely part of a vehicle's chassis or suspension. A red arrow points to a specific contact point between a metal component and a frame rail. The assembly includes several brass-colored bolts and nuts. A blue plastic component is visible on the right, and a red plastic component is on the left. The metal surfaces show signs of wear and dirt.